

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 30 Grid Reference: 335568 Map Sheet No. 82

Name of Owner/Quarry: \_\_\_\_\_

Working Pit/Disused Pit/New Locality: Some recent activity but small

Past Production: SEE REMARKS Estimated Reserves: ~~Large~~ Moderate.

Description of site: North of Barilla Rivulet. 300M N/W of Mt Rummy/Tasman Highway Junction

Limits to expansion: Creekbed. No other limits for 300M

Thickness of overburden: useful material extends to the surface

Sources of information: NB Field: 20.2.78 Laboratory: \_\_\_\_\_ Reference No: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): \_\_\_\_\_

Geological Description: Mudstone gravel and clay

History: Most of the hillside to the east of this pit has been scraped to a depth of 1/2 a metre at some time in the past. There is slow regrowth of scrappy vegetation.

Remarks: The most recent activity has been in the gully area. Present size 100 x 50 x 2M<sup>3</sup>. Expansion of this pit seems unlikely as there would be limited demand for such clayey gravel. Not Sampled