

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 31 Grid Reference: 341515 Map Sheet No. 82

Name of Owner/Quarry: Estate C.E. Goodwin Stonelease 648 P/M

Working Pit/Disused Pit/New Locality: Not operated for 9 months working on 8/12/78

Past Production: 200 x 100 x 30M³ Estimated Reserves: Equal + = Large

Description of site: North roadside Rokeby Road - Relatively unobtrusive from the road, other than the entrance.

Limits to expansion: S. Road Stone lease covers 10 acres.

Thickness of overburden: 30cm⁺ topsoil

Sources of information: RAAM 13.12.78 Field: 28.2.78 Laboratory: _____ Reference No: _____

Sizing analysis: T. SHIELDS Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1	75.0	53.0	37.5	26.5											
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Weathered dolerite rock. - Underlying several metres of Permian sandstone mudstone.

Used in sub-base course for road construction - eg sub-division work.

History: Was worked by Hobden previously. Housing Department also were involved. Two separate pits now joined

Remarks: New operated by Tas A. Shields & co. Used for base course and filling. Not sampled since most material greater than 75mm. Work face 30M high. Heavily fractured and requires benching.