

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 33 Grid Reference: 330553 Map Sheet No. 82

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: not worked for many years

Past Production: 100x100 x 1m³ ^{10,000} Estimated Reserves: V.S.

Description of site: up a gully to the North of the Tasman Highway near Sun Valley Motel, Warrane. Visible from the road.

Limits to expansion: none apparent

Thickness of overburden: gravelly material extends to the surface

Sources of information: WB Field: 28.2.78 Laboratory: _____ Reference No: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Mixed sandstone/mudstone gravel

History: _____

Remarks: Not worked for many years. Does not support much vegetation. Heavily eroded. Access track would no longer support loaded trucks