

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 36 Grid Reference: 247480 Map Sheet No. 82

Name of Owner/Quarry: Hobart City Council

Working Pit/Disused Pit/New Locality: Rehabilitated after use as a tip.  
*Amount quarried ≈ 20-40,000 m<sup>3</sup>.*

Past Production: 400 x 200 m<sup>2</sup> Area involved Estimated Reserves: Small. (southern part)

Description of site: 800 m west of Southern Outlet at Mt Nelson  
turnoff. *Never really a quarry, most material quarried for use in the tip.*

Limits to expansion: E. Road. N. Private property

Thickness of overburden: 20+ cm topsoil

Sources of information: RAAM WB Field: 7/12/78 28.2.78 Laboratory: \_\_\_\_\_ Reference No: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): \_\_\_\_\_

Geological Description: Varied material. Predominantly mudstone  
but some dolerite and granophyre at the northern end of  
this pit

History: Used over many years. Main use in the construction  
of Southern Outlet Rd. Used as a tip and now rehabilitated.  
The top of the tipping area has been grassed and some

Remarks: attempt has been made to level this area. There are  
3 separate levelled areas and the total area would exceed  
5Ha. Very suitable for a sporting complex but winds  
and weather could make this ~~unattractive~~ unattractive for  
this purpose.