

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 37a Grid Reference: 253490 Map Sheet No. 82

Name of Owner/Quarry: M. Bain - Proctors Road.

Working Pit/Disused Pit/New Locality: Overgrown. Disused for many years

Past Production: 120 x 40 x 40 m³ ^{192,000 m³} Estimated Reserves: Equal*

Description of site: South roadside, Proctor's Rd Dynnyrne

Limits to expansion: N. Road. S. Benching required, property boundary.

Thickness of overburden: 20m topsoil, 30m gravel

Sources of information: NB Field: 28.2.78 Laboratory: _____ Reference No: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1	75.0	53.0	37.5	26.5											
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Fresh Dolerite.

History: _____

Remarks: Since blasting and crushing are necessary for the successful operation of this pit, it is improbable that any the Environment Dept would issue a licence for further operation, so close to a built up area