

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 38 Grid Reference: 25/487 Map Sheet No. 87

Name of Owner/Quarry: M. Bain - Proctors Saddle.

Working Pit/Disused Pit/New Locality: Heavily eroded.

Past Production: 100x50x8m³ → 4000 m³. Estimated Reserves: Very Small.

Description of site: Shallow surface scraping operation on private property 200m West of Southern Cribbet, Mt Nelson Furness.

Limits to expansion: E. Road. N. Quarry. S. private property

Thickness of overburden: useful material extends to the surface

Sources of information: WB Field: 28.2.78 Laboratory: _____ Reference No: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Mudstone gravel

History: _____

Remarks: Disused for many years. Deep trench eroded through the centre of this pit