

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 39 Grid Reference: 220478 Map Sheet No. 82

Name of Owner/Quarry: Robsons City Council

Working Pit/Disused Pit/New Locality: Not worked for several years.

Past Production: 38,000 m<sup>3</sup> Estimated Reserves: moderate

Description of site: On the western side of Chimney Pot Hill. 500M East of junction of Huon Road and Ridgeway Rd.

Limits to expansion: None for 200m

Thickness of overburden: 10-20m gravelly topsoil

Sources of information: WB Field: 28.2.78 Laboratory: \_\_\_\_\_ Reference No: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1	75.0	53.0	37.5	26.5											
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): GR-GC.

Geological Description: ~~Quartzite~~ weathered dolerite gravel and clay

History: Used for roadworks in the Fern Tree and Ridgeway area. Not used since 1968 for any major work.

Remarks: Occasional use since then for filling material. Mostly used by council as a dumping ground for road reconstruction debris.

70x80 x 12 ÷ 2 (sloping).