

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 40 Grid Reference: 253497 Map Sheet No. 82

Name of Owner/Quarry: \_\_\_\_\_

Working Pit/Disused Pit/New Locality: Not worked 25 years +

Past Production: <sup>125,000 m<sup>3</sup> 28</sup> 120 x 40 x 30 m<sup>3</sup> Estimated Reserves: Equal + SEE REMARKS

Description of site: South Roadside, Waterworks Rd, Dynnyrne

Limits to expansion: N. Road. Surrounded by private property SEE REMARKS

Thickness of overburden: 20cm topsoil 20cm gravel

Sources of information: WB Field: 28.2.7 Laboratory: \_\_\_\_\_ Reference No: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1	75.0	53.0	37.5	26.5											
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): CR-AC

Geological Description: Fresh Dolerite - partly weathered dolerite

History: \_\_\_\_\_

Remarks: Further operation unlikely since blasting and crushing required and proximity to built up area makes the issue of a licence improbable  
Fenced off entirely by council.