

41

1116 P/M

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 41 Grid Reference: 011 663 Map Sheet No 82

Name of Owner/Quarry: E. Windsor

Working Pit/~~Disused Pit~~/New Locality: Only farm use now.

Past Production: 2000 m<sup>3</sup> Estimated Reserves: 1-10,000 m<sup>3</sup> (Small)

Description of site: E of hill scrap under transmission lines  
Just to the west of Johnny's Creek.

Limits to expansion: Topographical constraints.

Thickness of overburden: 20-40 cm slope deposits and soil.

Sources of information: RW+PA Field: 28/8/78 Laboratory: Reference No.:

Sizing analysis: Date:

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. P.I. L.S. D.R.

Special tests:

Group Symbol (unified soil classification system): GP

Geological Description: Crilled Dol Fine to medium platy dolerite.  
angular fragments up to 30cm long.  
In part slope deposits.

History: Used on farm & a small portion sold in the past.

Remarks: Sampled