

43

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 43 (a) Grid Reference 089 652 Map Sheet No 82

Name of Owner/Quarry: A.N.M. - Boyer (east)

Working Pit/Disused Pit/New Locality: Frequent use in immediate area.

Past Production: \_\_\_\_\_ Estimated Reserves: Moderate.

Description of site: Lies just to north of water pipeline. Scrapping and quarrying in and on the flanks of gully.

on hill to north of Boyer Road - access via reservoir track. Refuse disposal and bank dumping area.

Limits to expansion: None.

Thickness of overburden: between 10 cm and 100 cm - stony soil.

Sources of information: RAAM Field: 10/10/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	15.3	11.8	7.6	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1																	
2																	
3																	
4																	

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): GM

Geological Description: Permian mudstone gravel.

History: At present no carting away from site - material removed to bury wood waste.

Remarks: Material being used as overburden etc varies widely in character - sampling would be a useless exercise.