

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 51 Grid Reference 097 621 Map Sheet No 82

Name of Owner/Quarry: J. Beament "Alsenberg" - Malbina

Working Pit/Disused Pit/New Locality: Not used 15 years +

Past Production: 2500 m³ Estimated Reserves: Very small.

Description of site: Pit in gully in side of Buddins Hill.

Dam form base; slowly revegetating

Limits to expansion: Fence, property line - Nth

Thickness of overburden: 10-20 cm stony soil

Sources of information: RAAM Field: 14/6/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GM.

Geological Description: Siltstone gravel.

History: New Norfolk - Genton - Road.

Remarks: Dimensions