

55

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 55 Grid Reference 173 584 Map Sheet No 82

Name of Owner/Quarry: Colinsvale Rd - Glenlust.

Working Pit/Disused Pit/New Locality: Not worked 10+y.

Past Production: --- Estimated Reserves: Small

Description of site: Old limestone quarries on spur above the Colinsvale Road. In bush and rough cleared land.

Limits to expansion: Road.

Thickness of overburden: 25-50 cm decomposed limestone rock + soil.

Sources of information: RAM Field: 15/11/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	15.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GM-

Geological Description: Limestone Rubble

History: Old limestone quarry. Some may have been used as fill.

Remarks: Size of whole workings - 80x50 x 9.