

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 70 Grid Reference 252 480 Map Sheet No 82

Name of Owner/Quarry: Crown?:-

Working Pit/Disused Pit/New Locality: Not worked 10 years+

Past Production: 12,500 m<sup>3</sup> Estimated Reserves: Moderate

Description of site: Quarry at the saddle of the southern Outlet. Fronts Proctors road (east of). Surrounded by light timbered land.

Limits to expansion: None apparent behind face.

Thickness of overburden: = 20 cm stony soil. ~~But~~ <sup>hardest rock, lower</sup> 6m of face.

Sources of information: RAAM Field: 7/12/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	12.5	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): GP

Geological Description: Indurated mudstone - well bedded.

History: \_\_\_\_\_

Remarks: Some dumping of rubble and rubbish on quarry face.  
Lower Level 55x30x 6 = 6200  
Upper Level 50x25 x 5 = 6250