

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 72 Grid Reference 241 488 Map Sheet No 82Name of Owner/Quarry: Hobart City Council~~Working Pit/Disused Pit/New~~ Locality: Not used for 20 years.Past Production: 80,000 m³ Estimated Reserves: ModerateDescription of site: Roadside cuttings along Ridgeway Road following the bends in road. Either side of small creek.Limits to expansion: Environmental factors.Thickness of overburden: 25 cm of soil, 50 cm of overburden (rocky)Sources of information: RAAM Field: 7/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	9.5	7.6	6.0	4.75	3.75	3.0	2.5	2.0	1.5	1.18
	75.0	53.0	37.5	26.5													
1																	
2																	
3																	
4																	

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GP.Geological Description: Partly weathered dolerite.History: Used on Ridgeway road reconstruction in late 1950's.Remarks: Limited dumping of rubble on the cutting floor.
12 x 25 x 230 + 5 x 10 x 200.