

73

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 73 Grid Reference 193 586 Map Sheet No 82

Name of Owner/Quarry: R.E. Jaques - Berriedale.

Working Pit/Disused Pit/New Locality: Not worked 20 years +

Past Production: 1,900 m³ Estimated Reserves: Very Small

Description of site: Surface scrapings and eroded gullies in the hills behind Berriedale. at headwaters of Jaques Creek.

Limits to expansion: Environmental - (visibility, clear timbered land)

Thickness of overburden: 0-5 cm, very thin stony soil

Sources of information: RAAM Field: 7/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	12.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GM-SM

Geological Description: angular silty silstone gravel.

History: Local use

Remarks: 80x50 x .6.

Irregular very old workings, now partially revegetated with eucalypts reaching 10m in height.