

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 82 / 78 Grid Reference EN267619 Map Sheet No 82

Name of Owner/Quarry: METROPOLITAN WATER BOARD

Working Pit/Disused Pit/New Locality: only removal of stockpiled material

Past Production: 500 Estimated Reserves: V.S

Description of site: alongside of Risdon Brook Dam Road.

Limits to expansion: Risdon Brook road.

Thickness of overburden: 30 ~~cm~~ cm.

Sources of information: M.W.B. Field: \_\_\_\_\_ Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: 5/12/78

mm	76.2	50.8	38.1	25.4	19.0	15.3	11.8	7.6	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1																	
2																	
3																	
4																	

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): \_\_\_\_\_

Geological Description: weathered dolerite

History: \_\_\_\_\_

Remarks: \_\_\_\_\_