

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 82/83 Grid Reference EN 306568 Map Sheet No 8312Name of Owner/Quarry: CLARENCE COMMISSION.Working Pit/Disused Pit/New Locality: DPast Production: 30 x 45 x 3.5 = 4,700 Estimated Reserves: ModerateDescription of site: situated above Dam on Flagstaff road.Limits to expansion: Dam on west.Thickness of overburden: 20 cm stony brown soilSources of information: PR&M Field: _____ Laboratory: _____ Ref. No.: _____Sizing analysis: _____ Date: 20/12/78

mm	76.2	50.8	38.1	25.4	19.0	12.5	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1							100	96	90	85		80	75	66	
2							0	4	10	15		20	25	34	
3							0	4	6	5		5	5	9	
4															

L.L. 60% P.I. 33% L.S. _____ D.R. _____Special tests: M. B. D 16 cu/ft 100 - O. M. C % = 19.0

Group Symbol (unified soil classification system): _____

Geological Description: slightly weathered dolomite
most material only suitable for crushingHistory: material used for dam wall.Remarks: now used as dump for pipes etc.