

10a.

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 82/91 Grid Reference 094 622 Map Sheet No 82.

Name of Owner/Quarry: G. Johnson. - Malbina - Buddins Hill

Working Pit/Disused Pit/New Locality: Not worked for. 20y+.

Past Production: 900 m<sup>3</sup> Estimated Reserves: Very small.

Description of site: Subber Type scrapping down moderate hillside slope to the east.

Limits to expansion: none.

Thickness of overburden: N/A.

Sources of information: RAM Field: 14/1/78. Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): SM -

Geological Description: Siltstone Gravel.

History: Used for local use on tracks, race track.

Remarks: Hillside scan.

90x25 . 40.