

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 82/92 Grid Reference 091 616 Map Sheet No 82

Name of Owner/Quarry: George Johnson - Malbina

~~Working Pit/Disused Pit/New~~ Locality: As for 106

Past Production: 6000 m<sup>3</sup> Estimated Reserves: Small

Description of site: Largest surface scraping on hill. Two areas meeting at the base. Steep slope, visible from Highway

Limits to expansion: As for 106

Thickness of overburden: " " "

Sources of information: RAM Field: 8/12/78 Laboratory: Ref. No.:

Sizing analysis: Date:

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. P.I. L.S. D.R.

Special tests:

Group Symbol (unified soil classification system): SM - GM

Geological Description: Siltstone gravel.

History:

Remarks: 80x 35 x .6 + 100x 35 x 1.2

Sully Erosion