

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 82/92 Grid Reference 091 617 Map Sheet No 82

Name of Owner/Quarry: George Johnson - Malbina -

Working Pit/Disused Pit/New Locality: as for 10 b

Past Production: 3900 m<sup>3</sup> Estimated Reserves: Very Small

Description of site: Gully type surface scraping, passing under High Tension Lines. Westerly aspect. Includes several surrounding small pits.

Limits to expansion: None

Thickness of overburden: as for 10 b

Sources of information: RAAM Field: 8/12/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1			100	99	94	80	70	62			52			39	
2			0	1	6	20	30	38			48			61	
3			0	1	5	14	10	8			10			13	
4															

L.L. 30 P.I. 16 L.S. 8 D.R. -76

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): SM - GM.

Geological Description: Fine siltstone gravel.

History: \_\_\_\_\_

Remarks: 35 X 85 X 1.2 + 350 (lower down pits)

Gully erosion