

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 82/93 Grid Reference 088 622 Map Sheet No 82

Name of Owner/Quarry: George Johnson - Budding Hill - Malbina

Working Pit/Disused Pit/New Locality: Disused 7 10 6

Past Production: 2000 m<sup>3</sup> Estimated Reserves: Very small.

Description of site: Scraping reached on the upper of the two road. Track passes through sube. Steep slope - to W.

Limits to expansion: - Environmental aspects only

Thickness of overburden: 5-10 cm - stone

Sources of information: BSM Field: 8/12/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	7.6	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1																	
2																	
3																	
4																	

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): GM

Geological Description: Siltstone gravel.

History: \_\_\_\_\_

Remarks: 70 x 40 x 7