

S1

96

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 1 Grid Reference 257 407 Map Sheet No 82Name of Owner/Quarry: Kingston Beach.~~Working Pit/Disused Pit/New Locality:~~ Not worked 15 years +Past Production: 1000 m³ total Estimated Reserves: Small.Description of site: Hillside pits with N.E aspect above small new subdivision of Auburn Road Kingston. 200 m S.W of Reservoir.Limits to expansion: Housing development, scenic vista.Thickness of overburden: Thin root soil.Sources of information: RAAM Field: 6/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	15.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____


Special tests: _____

Group Symbol (unified soil classification system): SP.Geological Description: Fine white sand

History: _____

Remarks: Much eroded in parts ⇒ badland topography sampled.

254 393.



Derwent
King borough.

Howden Tindalox

F384

1973
1:12,500.