

S2.

97

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S2. Grid Reference 376 567 Map Sheet No 82

Name of Owner/Quarry: T. Walpole - Acton Road.

~~Working Pit/Disused Pit/New~~ Locality: Disused 10x7.

Past Production: ≈ 5000 m³ Estimated Reserves: Very Small

Description of site: corner block, fronting Acton Road. Newly fenced, carries patchy vegetation.

Limits to expansion: Roads (N.E. S.E) House, fences

Thickness of overburden: Useful material extends to surface

Sources of information: RASM Field: 20/12/78 Laboratory: DofM. Ref. No.:

Sizing analysis: _____ Date: _____

-212

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1								100	99.9	99.8		90	27	3	1
2												53			
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SF

Geological Description: - Quaternary fluvial sands with angular particles, grey colour, very little iron present.

History: Disused building sand pit (concrete).

Remarks: Now partly vegetated, *penus radialis* common.