

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S3 Grid Reference 392 523 Map Sheet No 82

Name of Owner/Quarry: V. Lowe - Acton Road.

~~Working Pit/Disused Pit/New~~ Locality: Not worked 10 y+

Past Production: 7,000 m³ Estimated Reserves: Very small.

Description of site: Denuded area on the west side of Acton Road. Just south of ~~Acton~~ Poultry farm.

Limits to expansion: Acton Road, House at rear, ^{Worked out} Environmental aspects,

Thickness of overburden: Useful ~~material~~ extends to surface.

Sources of information: PR. RAAM. Field: 20/12/78 Laboratory: P of M. Ref. No.:

Sizing analysis: _____ Date: _____

212

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1							100	99	99	99		94	40	9	4
2												74			
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SP

Geological Description: Quaternary fluvial sands, c angular particles, grey colour, little iron present sand-loam.

History: Used by the building industry.
may be partly filled in near future.
Was owned by Walker.

Remarks: 150 x 80 x .6

Worked out (down to indurated sand horizon) which is badly eroded. Fine sand washes downlope (eastwards) onto Acton road at times of heavy rain.