

5

100

860 P/M

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S 5 Grid Reference 403 454 Map Sheet No 82

Name of Owner/Quarry: A.H. Calvert.

Working Pit/Disused Pit/New Locality: Not worked 15y+

Past Production: 13,500 m³ Estimated Reserves: Small.

Description of site: Large pit at the rear of the Sandford hall and oval. Surrounded on three sides by scrub. Some patchy regrowth.

Limits to expansion: Oval (to the east)

Thickness of overburden: 40-70 cm of sandy clay.

Sources of information: RAM + PR Field: 2/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SC

Geological Description: Dark yellow clayey sand. Some ironstone buckshot gravel. Semi-lithified in most places.

History: _____

Remarks: Sampled.

65 x 80 x 2.5 - averaged dimensions