

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S23 * Grid Reference 395 527 Map Sheet No 82

Name of Owner/Quarry: Toronto Pastoral Company.

Working Pit/Disused Pit/New Locality: Not worked 47+

Past Production: 7,000 m³ Estimated Reserves: Small.

Description of site: Several pits and scrapings in fern-scrub land east of Acton Road.

Limits to expansion: No physical limits, other areas could be worked.

Thickness of overburden: 10-15 cm of black sands and root material

Sources of information: PR. RAAM Field: 20/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

cf 82098

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Light grey to white slight organic fine-med. sands lying above a sandstone.

History: _____

Remarks: Unlikely to be worked again in an increasingly residential area. Average thickness of extracted sand 35cm.