

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 82129 Grid Reference EN107604 Map Sheet No 83123

Name of Owner/Quarry FINLAYSON & BOON G

Working Pit/~~Disused~~ Pit/~~New~~ Locality: _____

Past Production: _____ Estimated Reserves Moderate

Description of site: Callins Cap Road Malenworth

Limits to expansion: _____

Thickness of overburden: _____

Sources of information: _____ Field: _____ Laboratory: _____ Ref.No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Building stone quarry in massive sandstone

History: _____

Remarks: _____