

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 1 Grid Reference 673 232 Map Sheet No 89

Name of Owner/Quarry: Crown - D.M.R.

Working Pit/Disused Pit/New Locality: Not worked 15y+. Present use as materials depot.

Past Production: 12,500 Estimated Reserves: Small.

Description of site: Irregular quarry in wet forest between the old Port Arthur-Nabona Road and a new deviation currently being built.

Limits to expansion: Roads (either side), need for dolomite rock - small.

Thickness of overburden: .5 - 1 m.

Sources of information: C S RAAM Field: 19/10/76 31/1/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	15.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): —

Geological Description: Fresh dolomite rock.
Some weathered material and bedded mudstone may be of use.

History: Not suitable for use on current works.

Remarks: _____