

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 2 Grid Reference 616 252 Map Sheet No 89

Name of Owner/Quarry: O.E. Hansen.

Working Pit/Disused Pit/New Locality: Not worked recently

Past Production: 19,000 m³ Estimated Reserves: Small-moderate

Description of site: Quarry in moderate slope of N-S. ridge along side the Stormlea Road, 300 m from its junction with the Dubana Rd.

Limits to expansion: None apparent (possibly property boundaries).

Thickness of overburden: 30 - 90 cm.

Sources of information: RAAM+PR Field: 31/1/79 Laboratory: PWD Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	9.5	7.5	6.0	4.75	3.75	3.0	2.5	2.0	1.5
	75.0	53.0	37.5	26.5												
1				100	95	89	80	67					35			19
2																
3																
4																

L.L. 50 P.I. 30 L.S. 12 D.R. .53

Special tests: _____

Group Symbol (unified soil classification system): GP-SP.

Geological Description: Well jointed (metamorphosed?) Permian siltstone. Dropstones common. Much material large and blocky.

History: Tasman Council in the past.

Remarks: Averaged dimensions - 35 x 60 x 9.