

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Quadrangle: 89 Serial NO: 12 Universal Grid Reference: 764 382

Name of Owner: Crown? Eaglehawk Neck Quarry

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable). Not worked 20y+

Past Production: 70x50x7 = 25000 m<sup>3</sup> Estimated Reserves: large moderate

Description of site: Nth side of Arthur Highway, nth of Eaglehawk Neck. Nth of small quarry - overgrown (marsh)

Limits to expansion: Arthur Highway, quality of material

Thickness of overburden: 30cm

Sources of information: Field 05-20-10-76 Laboratory:

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L.: P.I.: L.S.: D.R.:

Special Tests:

Group Symbol (unified soil classification system): GP

Geological Description:

silt stone, mudstone alternating bands of fissile and more massive siltstone. Prominently jointed. Some impure sandstone.

History: Old D.M.R. quarry

Remarks: No sample taken - info to be obtained from PWD

No material available for sampling - RTAM+PR 3/1/79