

15

1094 P/M

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 150 Grid Reference 409 389 Map Sheet No 89Name of Owner/Quarry: KJ^M Castle Musk's RdWorking Pit/Disused Pit/New Locality: Not worked for 8 years +Past Production: 4,000 m³ Estimated Reserves: SmallDescription of site: Patchy surface scrapings just to the east of Musk's Road near its junction with the South Arm Road. Top of hillock.Limits to expansion: Musk's Rd (west)Thickness of overburden: 0-10 cm stony soilSources of information: BAAH+R Field: 9/1/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1				100	98	90	66	50	37	32	30	28	23	15	
2				0	2	10	34	50	63	68	70	72	77	85	
3				0	2	8	24	16	13	5	2	2	5	8	
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GM.Geological Description: Siltstones and fine Sandstone - very impure.History: Not used since the arrival of present owners. - previously owned by Musk's. Possibly D.M.R. use.Remarks: Bushland.Sampled.Average depth of gravel worked 35 cm.