

21 ✓

864 P/M
~~864 P/M~~

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 21 Grid Reference 412 376 Map Sheet No 89

Name of Owner/Quarry: Charles Martin Constructions

Working Pit/Disused Pit/New Locality: Disused - 10 y +

Past Production: 5,000 m³ Estimated Reserves: small.

Description of site: One moderate sized pit and several smaller scrapings. Partly used as a dump.

Limits to expansion: None apparent. - little chance of further use.

Thickness of overburden: 20-30 cm grey sand

Sources of information: RAM-PR Field: 9/1/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.3	2.36	1.18	.60	.425	.355	.30	.212	.15	.075
1							100	99	98	93	84	59	23	11	6
2							0	1	2	7	16	41	77	89	94
3							0	1	1	5	9	25	36	12	5
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SP

Geological Description: Fine white sand, patches of light grey sand, and iron rich dark sands, some stony sections, some of which are calcite, others indurated sands.

History: Previously owned by J. Walker. - Present owner assumed tenancy about 1 year ago.

Remarks: Sampled. Average depth. 1 m.