

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 24 Grid Reference 709 359 Map Sheet No 89

Name of Owner/Quarry: \_\_\_\_\_ - Arthur Highway

Working Pit/Disused Pit/New Locality: Disused.

Past Production: 250 m<sup>3</sup> Estimated Reserves: Small.

Description of site: Eroded cutting in side of Arthur Highway.  
Removal of sand in the past.

Limits to expansion: Environmental aspects of roadside or scenic view.

Thickness of overburden: \_\_\_\_\_

Sources of information: RAGH APP Field: 2/2/79 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	15.0	9.53	4.76	2.36	1.18	.425	.30	.212	.180	.150	.075
1										TAKE	100	92	77	45	2.
2											0	8	23	55	98
3											0	8	15	32	43
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): SP

Geological Description: Podzolic soil profile. of several metres in depth. Grey sands 1m overlain by thicker yellow fine sand.

History: \_\_\_\_\_

Remarks: Yellow sand - sampled.

Probably won'ted illegally - and may lie on road reservation or being fronting private land.