

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 25 Grid Reference 621 328 Map Sheet No 89

Name of Owner/Quarry: B. Bannon - Premaydena.

Working Pit/Disused Pit/New Locality: Not worked for several years.

Past Production: 600m³ Estimated Reserves: S.

Description of site: Shallow partly grassed over sand pit under farms and pasture. Access by private road from Premaydena P.O.

Limits to expansion: None visible

Thickness of overburden: < 20 cm

Sources of information: RAM:AR Field: 2/2/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	7.5	4.76	2.36	1.18	0.60	0.425	0.30	.212	.150	.075
1												100	98	91	69	38	12
2												0	2	9	31	62	88
3												0	2	7	22	31	24
4																	

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SP - Sc

Geological Description: Pure fine white sand
8m over a hardpan.

History: _____

Remarks: 30 x 35 x 6 - Averaged Dimensions

Sampled.