

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN 168366

Quadrangle: 88 Serial No: 2 Co-ordinates: KmN KmE

Name of Owner: Maudsley - Crown - Gravel Reserve

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable)

Past Production: 20x50x30 = 20,000 Estimated Reserves: large

Description of site: By side of track which leads to dam. Not far from apple orchard. Have to drive thru this to reach pit.

Limits to expansion: track

Thickness of overburden: 0.5m

Sources of information: Field C.S. 16.3.76 Maudsley Laboratory

Sizing Analysis:

mm	75.0	53.0	27.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1					46	113	300	482	687	820		903	949	976	
2				100	95	89	70	52	31	18		10	5	2	
3															
4															

to

L.L: P.I: L.S: D.R:

Special Tests:

Group Symbol (unified soil classification system):

Geological Description:

weathered dolerite

History: Kingborough Council (?) have apparently used the pit in the past for roads, but now very little used. What is used is for small private jobs.

Remarks:

Vegetation is growing in pit, soil looks like no large quantities have been taken for at least 3-4 yrs. Area is used to dump a few tyres & a few pieces of cars. Quite a range in size of material, from fine up to 20cm diam. A few very large boulders of approx. 60cm diam. Did not attempt to sample for this reason.