

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN199285

Quadrangle: 88 Serial No: 4 Co-ordinates: KmN KmE

Name of Owner:

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).

Past Production: $20 \times 20 \times 4 = 1600m^3$ Estimated Reserves: small?

Description of site: Small pit on private property just off channel Hwy, not far south of Snug.

Limits to expansion: none apparent (small road)

Thickness of overburden: ?

Sources of information: Field C.S. 17.3.76 Laboratory

Sizing Analysis: Not located - RAAM. 10/4/79

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: P.I: L.S: D.R:

Special Tests:

Group Symbol (unified soil classification system):

Geological Description:

nth end like sedimentary layers at 45° angle. Matricial then changes - some dolomite (?) indurated sediment.

History:

Remarks: Hasn't been used for quite a few years, because trees 2m growing in floor.