

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN 045 344

Quadrangle: 88 Serial No: 8 Co-ordinates: KmN KmE

Name of Owner: Crown Land - Quarry Res.

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).

Past Production: 45 x 25 x 12 = 14900m³ Estimated Reserves: large

Description of site: By Cygnet Road right next to Iron Stone Creek.

Limits to expansion: Cygnet Road, a few homes, creek.

Thickness of overburden: approx. 0.5 m

Sources of information: Field C.S. 15.3.76 Laboratory P.W. Workers Council Clerk. R.9AM 15/3/79.

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: P.I: L.S: D.R:

Special Tests:

Group Symbol (unified soil classification system):

Geological Description: Dolerite rock dolerite - weathered in a few places but mostly fresh looking. Approx 75% blue in colour.

History: The pit once held a crusher. Work was stopped about 10 yrs ago. Reason for this I don't know.

Remarks: Material used for road surface (?) - crushing required Highest face. 20m Average 12m.