

9

Q

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN190126

Quadrangle: 88 Serial No: 9a Co-ordinates: KmN KmE

Name of Owner: L. Woodward

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable). *Not worked 5 years +*

Past Production: 20x15x10 = 3000m Estimated Reserves: *moderate*

Description of site: *Hillside site, Wolfs Rd Middleton (on southern side, up winding section) called Risby Road on signpost*

Limits to expansion: *Wolfs Road*

Thickness of overburden: *0.5m*

Sources of information: Field *C.S. 18.3.76* Laboratory

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1					100	98	82	56			15			9	
2		100		97		95	88.9	64.1	36.5	22.4		18.4	11.9	8	
3		0		3		95.7	11	36	63	78		95	88	92	
4		0		3		1	7	25	27	15		7	3	4	

A  
B

6  
Dom  
2113/4  
10

L.L: 37 P.I: 20 L.S: 8 D.R: 0.59

Special Tests:

Group Symbol (unified soil classification system): *SW-SC*

Geological Description: *highly weathered dolomite c. yellow colouring decomposed dolomite - PWD. clayey grit and soft sometimes shattered spheroidally weathered boulders.*

History: *about 20-30 yrs old. Council has used material from this pit, but later rejected it in preference to one at Mardon.*

Remarks: *Pit only used now for small private jobs.*