

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Quadrangle: 83 Serial No: 15 Co-ordinates: EN 032 351

Name of Owner: Huonville Council

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable)

Past Production: 150 x 55 x 12 = 100,000 m³ Estimated Reserves: large but for scenic road

Description of site: By scenic road on hillside overlooking Huonville Bridge. Lightly wooded area.

Limits to expansion: Scenic Road bounds on both top & bottom of pits smaller pit at one end.

Thickness of overburden: < 1m

Sources of information: Field C.S. 15.3.76 P.W. workers Council Clerk Laboratory D.M.R.

Sizing Analysis:

mm	75.0	53.0	27.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1				100	92	72	57	41			18			9	
2															
3															
4															

L.L: 4A P.I: 21 L.S: 10 D.R: 49

Special Tests:

Group Symbol (unified soil classification system): SW-SC

Geological Description: unweathered dolomite with few very large boulders. - Mainly fine to medium silty angular gravel.

History: Pit created by Huon Council about 18 yrs back & has been worked on and off since then for road works. Council quarry material never leaves municipality.

Remarks: Originally was two separate pits, but now one large one with about four benches. Presently being worked by P.W.D for fill and surface on the Franklin Road.