

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Quadrangle: 88 Serial No: 16 Co-ordinates: EN 072 315  
 Name of Owner: P.W.D. (?) & COUNCIL (?) - Crown: Gravel Reserve  
 Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable) not worked 4y4  
 Past Production: 15 x 60 x 25 = 2,250 m<sup>3</sup> Estimated Reserves: large  
 Description of site: By Pelverata Rd, cut into hillside, scrub lies behind.  
 Limits to expansion: Pelverata Road (not near the face)  
 Thickness of overburden: 0.5 - 1 m, in some places weathered down slope rubble.  
 Sources of information: Field C.S. 16-3-76 Laboratory D.M.R.  
R.M. 75-3-79

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1			100	99	92	73	56	43			28			15	
2															
3															
4															

L.L: 48 P.I: 27 L.S: 13 D.R: 55

Special Tests: .....

Group Symbol (unified soil classification system): GP - G.C.

Geological Description: partly weathered dolerite - fine blocky rock.

History: Probably used in construction of Pelverata Road, and repair work to same. No vegetation, so most likely still being used when necessary.

Remarks: Not many large boulders around - 60-70% of material approx. 4-8 cm in diam. Shouldn't think it would be much good for surface work.