

18 ✓

F

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN 271 340

Quadrangle: 38 Serial No: 18 Co-ordinates: KmN KmE

Name of Owner: E.M. Hale STONE WARE 873 P/M ✓

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).

Past Production: 50x20x10=10,000m³ Estimated Reserves: - moderate.

Description of site: On Western side of Linderbox Rd between Lucas Point and Piersons Point. Cut into hillside.

Limits to expansion: Linder Box Road, private property.

Thickness of overburden: 40.5m

Sources of information: Field C.S. 16.3.76 H. Hale Laboratory

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1		100	88	69	52	40	31	25			16			9	
2															
3															
4															

L.L: 46 P.I: 24 L.S: 10 D.R: 0.55

Special Tests:

Group Symbol (unified soil classification system): GP-GC

Geological Description: weathered dolerite - PWD

History: Pit started 8-10 yrs ago and has been in continuous use. A crusher operated in this pit, but was stopped 12-18 mths ago by Mines Dept. because it was too close to the road.

Remarks: Hazell Bros pushes out material because Hale has no bulldozer. Material is taken (most) by Mr Wells who is a contractor - he uses material for road base & roads within subdivisions. A few large boulders with 20-30 cm diameter, but majority of material 4-10 cm diameter.