

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN 271 340

Quadrangle: 88 Serial No: 19 Co-ordinates: KmN KmE

Name of Owner: E.M. Hale STONE LEASE 873 P/M ✓

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).

Past Production: 15 x 20 x 20 = 6,000 m<sup>3</sup> Estimated Reserves: Large?

Description of site: On west side of Jindubox Road between Lucas Pt. and Piersons Pt. Cut into hillside next to larger quarry.

Limits to expansion: Jindubox Road, Private property.

Thickness of overburden: 40.5m

Sources of information: Field C.S. 1637b H. Hale Laboratory

Sizing Analysis:

mm	75.0	53.0	27.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: P.I: L.S: D.R:

Special Tests:

Group Symbol (unified soil classification system):

Geological Description:

weathered dolomite

History: Pit started 8-10 yrs ago by Hale has been in continual use for that time.

Remarks: Here also Hazell Bros pushes out material and Hales son, H. Hale carts this material. Main use is for driveways for new homes being built in area.