

24 ✓

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 98/24 Grid Reference 270342 Map Sheet No. _____

Name of Owner/Quarry: Kingborough Council

Working Pit/Disused Pit/New Locality: D

Past Production: 4000 Estimated Reserves: 2

Description of site: western side of Tinder Box Road between Lucas Point and Piersons Point

Limits to expansion: Tinder Box Road.

Thickness of overburden: 1/2 metre

Sources of information: PRMN* Field: _____ Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: 14/12/78

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1	100	76	56		33	24	17	14	11	9		7	5	4	
2	0	24	44		62	76	83	86	89	91		93	95	96	
3	0	24	20		18	14	7	3	3	2		2	2	1	
4															

12

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GP

Geological Description: weathered dolerite

History: Once used for building breakwater at Tinder Box about 30 yrs ago but material was washed away

Remarks: sampled.
used for potholes on Tinder Box and Bowden Road.