

38

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN 215 356

Quadrangle: 88 Serial No: 38 Co-ordinates: KmN KmE

Name of Owner: King Council (?)

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable) Rehabilitated

Past Production: 150x30x3 Estimated Reserves: nil

Description of site: Str boundary, Channel H'way, margate

Limits to expansion: Channel H'way, homes

Thickness of overburden: nil

Sources of information: Field C.S. / V.T. 243-76 Laboratory

Sizing Analysis:

mm	75.0	53.0	27.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: P.I: L.S: D.R:

Special Tests:

Group Symbol (unified soil classification system):

Geological Description: silt stone - massive bed, separated by thin shale bands. Slightly dipping.

History: Now being filled in by clean fill and rubble.

Remarks: Has not been used for at least 20yrs - overgrown trees - rubbish also about. Sample not taken.