

421

X

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Quadrangle: 88 Serial NO: 42 Universal Grid Reference: 042 113

Name of Owner: Crown Land?

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable). *not worked for several years.*

Past Production: 80x50x4 } = 20,000m<sup>3</sup> Estimated Reserves: *indicate.*

Description of site: By side of Esperance Coast Road at Yarnny Subbens Bay

Limits to expansion: Esperance Coast Road

Thickness of overburden: nil

Sources of information: Field C.S. 20-7-76 Laboratory:

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1		100	92	85	80	73	57	39			16			9	
2															
3															
4															

L.L.: 33 P.I.: 14 L.S.: 6 D.R.: 53

Special Tests:

Group Symbol (unified soil classification system): SW-SC

Geological Description: weathered dolomite decomposed dolomite - PWD ✓

History:

Remarks: Sample taken from pit. Pit has two sections (an upper and lower section) both with separate access.