

44

84

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Quadrangle: 88 Serial NO: 44 Universal Grid Reference: 115 188

Name of Owner: Cowen's Quarry

Working Pit / ~~Disused Pit~~ / New Locality: (Delete whichever inapplicable)

Past Production: 50x25 x 12 = 15000m³ Estimated Reserves: large

Description of site: Stray Woodbridge Hill Rd. Next turn to south of East of Cowen Road.

Limits to expansion: none apparent

Thickness of overburden: 10cm

Sources of information: Field CS-28-9-76 Laboratory: 24.8.1977

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1			100	97	92	81	63	44			19			11	
2															
3															
4															

L.L.: 40 P.I.: 24 L.S.: !! D.R.: 0.60

Special Tests:

Group Symbol (unified soil classification system): SP-SC

Geological Description: DECOMPOSED DOLERITE GRAVEL
moderately weathered dolerite

History: Old bygone council, occasional private use
D.M.R. use?

Remarks: No sample taken - info to be obtained from PWD

8

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Quadrangle: 88 Serial No: 44 Co-ordinates: 115188 KmN..... KmE
 Name of Owner:
 Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).
 Past Production: 50x75x20 M. Estimated Reserves: EQUAL +
 Description of site: GARDNERS BAY / WOODBRIDGE RD. (EAST)

 Limits to expansion: NONE OBVIOUS - BLASTING OF ROCK FACE?
 Thickness of overburden: 0.5 M.
 Sources of information: Field WB 28.7.77 Laboratory 24.8.1977

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: P.I: L.S: D.R:.....

Special Tests:

Group Symbol (unified soil classification system):

Geological Description: WELL FRACTURED DOLEKITE

History:

Remarks: BAD ACCESS. USED AS LOCALS RUBBISH DUMP.
SAMPLE TAKEN FROM MOST RECENT LOOKING HEAP.