

46

1069 P/M  
WARK, A.S.

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 46 Grid Reference 186380 Map Sheet No 58

Name of Owner/Quarry: \_\_\_\_\_

Working Pit/Disused Pit/New Locality: O.W.

Past Production: 1,600 m<sup>3</sup> Estimated Reserves: M-L

Description of site: VAN MOREY ROAD, hillside pit, eastern side of road, just before sharp bend to the west in road. Surrounded by light bush.

Limits to expansion: VAN MOREY ROAD - no limits in bushland.

Thickness of overburden: less than 30 cm.

Sources of information: PRYNN Field: \_\_\_\_\_ Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: 14/12/78  
1/2/79

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): GP-GC

Geological Description: weathered dolomite - moderately - highly weathered  
⇒ spheroidally weathered (soft) boulders and angular dolomite grit.

History: \_\_\_\_\_

Remarks: Sampled.

Dimensions 40 x 20 x 2.

Narrow entrance dug into bank.