

51J

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 88/51 Grid Reference 189353 Map Sheet No 88

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: Not worked for several years.

Past Production: 20x 10 x 2-200m³ Estimated Reserves: L

Description of site: Pit situated just ^{east} NIERINNA RD. in gully sloping scrub bank. In area divided for low density housing.

Limits to expansion: NIERINNA RD to the North.

Thickness of overburden: 20cm.

Sources of information: P.R+RM. Field: 1/2/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1		100	92		86	79	63	42	28	21	19	17	13	9	..
2		0	8		14	21	37	58	72	79	81	83	87	91	
3		0	8		6	7	16	21	14	7	2	2	4	4	
4															

L.L. _____ P.I. _____ L.S. _____ D.R. 53

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: very weathered Dolerite.

* History: Indicated on D. of Envr Science to ~~not~~ be used by D.M.R. for 10,000 ton/yr.

Remarks: Pit probably opened just for filling pot holes. Sampled.