

55

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 55 Grid Reference 078 326 Map Sheet No 88

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: Not worked 8 years +

Past Production: 1200 m³ Estimated Reserves: moderate

Description of site: Roadside cutting dug deeper into hillside (low) to give small pit. Banked by light natural vegetation.

Limits to expansion: None apparent in hillside.

Thickness of overburden: 40 cm soil

Sources of information: RAAM Field: 15/3/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Slightly weathered dolomite rock, fractured \Rightarrow blocky dolomite.

History: Used for base for Pelvata Road in immediate area.

Remarks: Approximate average dimensions 25x20x2.5 + 150m³. No material to sample.