

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 57 Grid Reference 144 387 Map Sheet No 88

Name of Owner/Quarry: R. Oates + P.F. Dillon. - Sandfly

Working Pit/Disused Pit/New Locality: O.W.

Past Production: 2.700 Estimated Reserves: Moderate.

Description of site: On end of ridge bounded by hairpin bend of farm track. E. side of Pelicarta Road. Gate just off road.

Limits to expansion: Road (on three sides)

Thickness of overburden: ~15cm (all cleared off)

Sources of information: _____ Field: 15/3/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	12.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GR

Geological Description: Angular, blocky dolerite (coarse) gravel with moderate amount of clayey fines.

History: Used on access roads.

Remarks: 30x45 x 2.